03500.015453.

PATENT

ATES PATENT AND TRADEMARK OFFICE

In re Patent of: Examiner: L. Liang MASAHIKO KUBOTA, et al. Group Art Unit: 2853 Application No.: 10/646,700 Filed: August 25, 2003 For: SOLID SEMICONDUCTOR ELEMENT,) INK TANK, INK JET RECORDING APPARATUS PROVIDED WITH INK TANK, LIOUID INFORMATION ACQUIRING METHOD AND LIQUID PHYSICAL PROPERTY CHANGE DISCRIMINATING METHOD U.S. Patent No.: 7,210,755 December 10, 2007 Issued: May 1, 2007 Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION **UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

> 12/12/2007 AWONDAF1 00000017 7210755 100.00 OP 01 FC:1811

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Michael K. O'Neill

Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 1802283v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,210,755

DATED

May 1, 2007

INVENTOR(S) :

Masahiko Kubota, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 7, "se miconductor" should read --semiconductor--.

COLUMN 27

Line 1, "constant ϵ " should read --constant ϵ --.

COLUMN 31

Line 13, "change AR" should read --change ΔR --.

COLUMN 32

Line 24, "vale" should read --valve--.

COLUMN 43

Line 52, "21 and" should read --211 and--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>7,210,755</u>

No. of add'l. copies @ 30¢ per page

DFC 13 200%

■

Form PTO 1050 (Rev. 3-82) (Form#30)

FCHS_WS 1802304 v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

7,210,755

DATED

May 1, 2007

INVENTOR(S) :

Masahiko Kubota, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 7, "se miconductor" should read --semiconductor--.

COLUMN 27

Line 1, "constant ϵ " should read --constant ϵ --.

COLUMN 31

Line 13, "change AR" should read --change ΔR --.

COLUMN 32

Line 24, "vale" should read --valve--.

COLUMN 43

Line 52, "21 and" should read --211 and--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) FCHS_WS 1802304 v1 **PATENT NO.** _7,210,755

No. of add'l. copies @ 30¢ per page

DEC 13 2007

<u>_____</u>